

Basic Vehicle Condition Guide

Report ID: 17,265,986


Version:

Created: 22 Jan 2018

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2,002 Registration: ANR237 Reg Expiry: 27 Feb 2018 WoF Expiry: **Odometer:** 05 Oct 2018 **Good No:** 440,838 Kms 17265986 VIN: MMBJNK7702D03948 **Next Service: Service History:** 448,000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Paint fade on bonnets, rust on all door sills, rust around keyhole.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|--|--|--|
| Seats | hole in drivers seat,rip in back seats | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Inspected by: Donovan Matara

| | | , | , |
|------------------------------|-----------------|---------|-----|
| | Pass | Fail | N/A |
| Engine | | 1 | |
| Oil level | ~ | | |
| Smoke & fumes | \(\triangle \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | • | • |
| Operation | ~ | | |
| Noise | \(\times \) | | |
| Clutch | ~ | | |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | 25) |
| Left front | · · | 5 | mm |
| Right front | | | mm |
| Left rear | 3 | | mm |
| Right rear | <u> </u> | | mm |
| Spare | | | |
| Suspension | | Yes | |
| Suspension performance | | | |
| Steering performance | \(\triangle \) | | |
| Shock absorbers | | | |
| | <i>V</i> | | |
| Air Conditioning / Heater | | | |
| Operation | | • | |
| Electrical / Accessories | | | I |
| Head lights | • | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | \(\times \) | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | | | ~ |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| Date: 22 Jan 201 | | | |

I have read and understood this condition guide.

Name:

Signature:

Date: 22 Jan 2018