

Report ID: 17,267,025 Version: 1 Created: 22 Jan 2018

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2,012	Registration:	GLD785	Reg Expiry:	16 Jul 2018	Engine		. un	
WoF Expiry:		Odometer:		Good No:	17267025	Oil level	~		
VIN:		Next Service:	79,766 Kms	Service Histor		Smoke & fumes			
V II 4.	MMAJNKB40CD01441	NEXT SELVICE.	89,698	Service mistor	V: No		~		
Note: This report is not a warranty						Performance	~		
	a guide only. Conside					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
	• •	•	5		5	Coolant condition	~		
Key:	SC	\sim	W S		S R P	Performance	~		
S = scratch		$\overline{(0)}$		5(O)7		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	s AR			10		Operation	~		
PT = paint def	ect NP				111/1	Noise	~		
C = crack						Clutch	~		
P = pin dent	HIP				7414	CV joints	~		
* = decals	sc 916			TO	ED SPW	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs w						Performance	~		
		Note: son	ne defects & blemishes	may not be disp		Hand Brake	~		+
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
Headlights need attention						Tyres (lowest observed tread depth of tyres)			
						Left front		0	mm
						Right front	1	0	mm
						Left rear	1	0	mm
Conditions During Body Inspection: Wet						Right rear	1	0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
۱ ۲						Operation	~		
Interior Comments						Electrical / Accessories	1		1
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Faileis						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		<u> </u>
						Window winder FL Window winder FR			
General (Comments						~		
	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 22 Jan 2018									
I have read	and understood th	is condition c	guide. Name: .			Signature:			