

Report ID: 17,270,246 Version: 3 19 Feb 2018 Created:

Make:	Ford	Model:	Falcon	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,013	<b>Registration:</b>	GRZ315	<b>Reg Expiry:</b>	31 Mar 2018	Engine		1	
WoF Expiry:	08 Feb 2019	Odometer:	100,022 Kms	Good No:	17270246	Oil level	~		
VIN:	6FPAAAJGSWCS99169	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	S P	-M-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	Transmission		
D = dent R = rust	s sc			715	HIL	Operation	~		
PT = paint defe	ect NP	F		$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				거네	CV joints	~		-
* = decals	sc 916			-No-	AID	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W P P W D						Performance	~		
Dealer		Note: son	ne defects & blemishes	may not be disc	blayed in the diagram	Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread	· ·	oftvre	L
Windscreen chips						Left front 5 m			
						Right front		5	mm
						Left rear			mm
						Right rear	· · · · · · · · · · · · · · · · · · ·		
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
						Suspension performance	~		1
						Steering performance		~	
						Shock absorbers	~	•	-
						Air Conditioning / Heater	v		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		1
Seals						Tail lights	~		
Carpets	Average						~		
	Good								
Panels						Dashboard warning lights	<b>v</b>		
Dashboa	Ird Good					Wipers (front & rear) Window winder FL	<b>v</b>		
							<b>v</b>		
General (	Comments					Window winder FR	~		
Vehicle pulls left						Window winder RL	<b>v</b>		
						Window winder RR	<b>v</b>		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timina	Chain			Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Lvidence			lot Applicable	11113.		Reversing camera			~
Inspected by: John Lindsay Date:							18		

I have read and understood this condition guide.

Name: .....

Signature: .....