

I have read and understood this condition guide.

Report ID: 17,322,133 Version: 1 Created: 25 Jan 2018

Signature:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
	2,016	Registration:	KCP900	Reg Expiry:	12 Jan 2018	Engine			
WoF Expiry:	13 Oct 2019	Odometer:	51,054 Kms	Good No:	17322133	Oil level	~		
VIN:	MR0KA3CD801301679	Next Service:	60,000kms	Service History	/: Yes	Smoke & fumes	~		
						Performance	~		
	ort is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechani	cal inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S D SC S S S S S S S S S S S S S S S S						Operation 🖌			
PT = paint defect						Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIR				2414	CV joints	~		
* = decals	sc 916			The second	ED SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant			W			Performance	~		
Body Insp	action Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some delects & blemisnes may not be displayed in the diagram Fine chips on screen. Fine chips on screen.						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front 4 r			mm
						Right front	4	4	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare Yes		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension	uspension		
Tidy & dry.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboar	a					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Nice smooth driving 4x4 d/cab ute.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
			-			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of	of Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 25 Jan 2018									
							5		

Name: