

Basic Vehicle Condition Guide

Report ID: 17,322,817

Pass

1

/

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 26 Jan 2018

Fail

N/A

1

mm

mm

mm

 mm

5.5

5.5

Yes

Make: Model: B180 **Body Style:** Hatchback Mercedes-Benz

Year: 2,010

WoF Expiry:

Registration: **Odometer:**

Good No: 17322817

Reg Expiry:

VIN: **Next Service:** WDD2452322J636582


Service History:

Note: This report is not a warranty

16 Jan 2019

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

44,376 Kms



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Over seas Nav system.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Suspension				
Suspension performance	~			
Steering performance	<i>v</i>			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V V			
Dashboard warning lights				
Wipers (front & rear)	V			
Window winder FL				
Window winder FR	~			
Window winder RL	~			
Window winder RR	V			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1	,		
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			~	
Date: 26 Jan 2018				
-				

I have read and understood this condition guide.

Eddie Marsters

Name: