

Report ID: 17,343,181 Version: 1 Created: 08 Feb 2018

Make:	Nissan	Model:	Fuga	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2,005	05 Registration: Reg Expiry:				Engine				
WoF Expiry:	29 Jan 2019	Odometer:	108,254 Kms	Good No:	17343181	Oil level	~			
VIN:	7AT0DH8GX1821528(Next Service:	118250kms	Service Histor	' y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	t been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission			I	
D = dent R = rust						Operation	~			
PT = paint defe		F		$\left(\left \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HID				74114	CV joints			~	
* = decals	- Alf			-No-		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
Padulaa		Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tre	ad depth	of tyre	es)	
									mm	
						Right front		5	mm	
						Left rear		5	mm	
Condition	as During Body Insi	pection:				Right rear		5	mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Tidy and dr	у.					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
		Air Conditioning / Heater								
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	Guu					Indicators	· ·			
Panels	Good					Dashboard warning light:	-			
	, Good					Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	I					Window winder FR	~			
General Comments						Window winder RL	~			
Good driving, smooth sedan.						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2	I	1	
Road Conditions During Test Drive: Dry						Central locking	· ·			
						Remote locking	· ·			
Engine Ti	Sat. Nav. (basic test only)	+		~						
Evidence	of Cam Belt Replac	Reversing camera	~							
Inspected by: Daryll Timms Date: 08 Feb 2018										

I have read and understood this condition guide.

Name:

Signature: