

Report ID: 17,344,865 Version: 3 26 Jul 2018 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2,010	Registration:	FSC25	Reg Expiry:	13 Sep 2018	Engine			
WoF Expiry:	10 Feb 2019	Odometer:	218,700 Kms	Good No:	17344865	Oil level	~		
VIN:	MR0HZ29G604019814	Next Service:	228500	Service History	V: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0	SC W D		SC W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch	~		
P = pin dent						CV joints	~		
* = decals SSC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
Note: come defecte & blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments							•	ofture	
Drivers wing mirror broken						Tyres (lowest observed tread depth of tyres)			
						Left front	2.		mm
						Right front	2.		mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carnage & onder bonnet inspection comments						Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories			
Seats	Avelage					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
	-					Window winder FR	<		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	<		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 15	0,350	Reversing camera	~		
Inspected by: Dion Mair Date: 14 Feb 2018									
I have read and understood this condition guide. Name:									

I have read and understood this condition guide.

Name: