

Report ID: 17,354,042 Version: 1 15 Feb 2018 Created:

Make:	Toyota	Model:	Hiace	Body Style:	Minibus		Pass	Fail	N/A
Year:	2,001	Registration:	ZX6770	Reg Expiry:	25 Oct 2018	Engine		L	
WoF Expiry:	30 Oct 2018	Odometer:	257,602 Kms	Good No:	17354042	Oil level	~		
VIN:	JT721LHB300190212	Next Service:	256000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SD		<u>SD</u>	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust				710	HIV	Operation	~		
PT = paint def	ect NP				70111	Noise	~		
C = crack					S D SC	Clutch	~		
P = pin dent	HE				74 <u>11</u> 4	CV joints			~
* = decals	sc Ole	10		To .	ED SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S R S D						Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Front bullbar bent						Tyres (lowest observed tread depth of tyres)			
					Left front 6 mm				
						Right front		7	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
	poor.	holes RF				Wipers (front & rear)	~		
Dashboa	rd					Window winder FL			~
						Window winder FR			~
General Comments						Window winder RL			~
Drives OK						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 15 Feb 2018									
Date: 15 Feb 2018									

I have read and understood this condition guide.

Name:

Signature: