

Report ID: 17,356,142 Version: 1 16 Feb 2018 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2,013	Registration:	HAC306	Reg Expiry:	05 Jan 2019	Engine				
WoF Expiry:	15 Aug 2018	Odometer:	92,800 Kms	Good No:	17356142	Oil level	~			
VIN:	WF0EXXGBBEDU0928	Next Service:	98000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and ti	his can be arranged to	r an additional c	narge.	Coolant condition	~			
	SC					Performance	~			
Key:		=		5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
R = rust	w AK			210		Operation	~			
PT = paint def	ect NP				ארור	Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	HIP				7414	CV joints	~			
*= decals SC 99 SC						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
w = significan			SC W			Performance	~			
Body Inst	paction Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments Stone chips front screen.						Tyres (lowest observed tread	d depth	of tyre	s)	
Stone emps none serveri.						Left front 5 mr			mm	
						Right front	6		mm	
						Left rear			mm	
Conditions During Body Inspection: Dry						Right rear	5 mm		mm	
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Good.						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			L	
L						Operation				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Cood					Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	1					Window winder FR	~			
General Comments						Window winder RL	~			
Nice tidy car runs well.						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	2 V			
Road Conditions During Test Drive: Dry						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected by: Brian Hill Date: 16 Feb 2018										

I have read and understood this condition guide.

Name:

Signature: