

Report ID: 17,358,403 Version: 2 Created: 20 Feb 2018

Make:	Toyota	Model:	Lucida	Body Style:	Van		Pass	Fail	N/A
Year:	1,993	Registration: CHN793 Reg Expiry: 07 Apr 2018		-	Engine	I	I		
WoF Expiry:	10 Mar 2018	Odometer:	250,227 Kms	Good No:	17358403	Oil level	~		
VIN:	7A8H61P0704065188	Next Service:	184000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	r		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	r		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SPT	-0	S D		<u>SD</u>	Radiator / Hoses (visual)	~		
S = scratch						Transmission	I		
D = dent R = rust						Operation	~		
PT = paint defect						Noise	r		
C = crack						Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	r		
SC = stone chips						Brakes			
W = significant scuffs S S S D S S S D S						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			es)
						Left front		2 mm	
						Right front		2	mm
						Left rear		4	mm
Conditio	ns During Body Ins	oection:	Dry			Right rear		4	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Very dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	1
L]						Operation		~	
Interior Comments						Electrical / Accessories	1		
Seats	Poor					Head lights	~		
	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
	Poor					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Oil change	light on plus other fault	lights				Window winder RR			۲
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 20 Feb 2018									
Date: 20 Feb 2018									
I have read and understood this condition guide. Name:									