

Report ID: 17,363,254 Version: 2 Created: 03 May 2018

Make:	Holden	Model:	Rodeo 4X2	Body Style:	Utility		Pass	Fail	N/A
Year:	2,004	Registration:	CBA926	Reg Expiry:	05 Jul 2018	Engine			L
WoF Expiry:	,	Odometer:	331,279 Kms	Good No:	17363254	Oil level	~		
VIN:	MPATFR77H4H52888;	Next Service:	333000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S D SC		S D			Performance	~		
Key:	ISDSC IL	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SD AR			20		Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack						Clutch	~		
P = pin dent	s sc dl				2416	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	S D SC		S D SC		S D	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Aerials attached to the RF,LF guards, LH sill dented ,						Tyres (lowest observed tread depth of tyres)			
						Left front	7 mm		mm
						Right front	7	7	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance						~			
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	drivers sea	t ripped,worn ,				Head lights	~		
Carpots	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Daabbaa	pocket mi	ssing under stere	90,			Wipers (front & rear)	~		
Dashboa	iu i					Window winder FL	~		
						Window winder FR	<		
<u>General Comments</u>						Window winder RL			~
Noisey belt	S ,					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	Central locking	<							
Road Conditions During Test Drive: Dry						Remote locking			<
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 03 May 2018									
Inspected by. Donovan matara Date: 05 Midy 2018									

I have read and understood this condition guide.

Name:

Signature: