

Report ID: 17,366,294 Version: 1 20 Mar 2018 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,008	<b>Registration:</b>	ESD739	Reg Expiry:	20 Oct 2018	Engine			
WoF Expiry:	16 Dec 2018	Odometer:	247,163 Kms	Good No:	17366294	Oil level	~		
VIN:	JM0GH10F100120352	Next Service:	248000	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:	S SC	-0	S D SC S D SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			1n-	EID SSC	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint defe C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	s sc PIP			AL.	EIRS	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S D SC S D SC S D						Performance			
		Noto: com	ne defects & blemishes				~		
Body Insp	pection Comments	Note: son	le délects & biemisnes	may not be disp	nayed in the diagram	Hand Brake	<ul> <li></li> </ul>	. (	
Stone chip in the windscreen ,LR hub cap missing ,						Tyres (lowest observed tread depth of tyres)			
						Left front	6		mm
						Right front	5	5	mm
[						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Under Ca	rriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Correcto	Average					Tail lights	~		
Carpets						Indicators	<		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry									
						Remote locking	~		
						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									- <b>-</b>
Inspected by: Donovan Matara Date: 20 Mar 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....