

Report ID: 17,369,039 Version: 1 17 Mar 2018 Created:

Make:	Suzuki	Model:	SX4	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,012	Registration:	LEW869	Reg Expiry:	01 Jul 2018	Engine	1		L
WoF Expiry:	19 Mar 2019	Odometer:	119,309 Kms	Good No:	17369039	Oil level	~		
VIN:	JSAGYB51S00310256	Next Service:	125,762kms	Service Histor	y: Yes	Smoke & fumes	V		
						Performance	r		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	V		
						Performance	~		
Key:	SC S	<u>~</u> ⊘	SW S	-01-	s	Radiator / Hoses (visual)	~		<u> </u>
S = scratch						Transmission			
D = dent	s sc			TIN	SW	Operation	~		
R = rust PT = paint def				\prod	JUIL	Noise	~		
C = crack					SC	Clutch	~		
P = pin dent						CV joints	~		
* = decals	SRPSC 916			The	EIP sw	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC S W S W						Performance	~		
		Noto: con	he defects & blemishes			Hand Brake	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								oftwo	
Stone chipping on front windscreen.						Left front	res (lowest observed tread depth of tyres)		
							7.		mm
						Right front Left rear	7.		mm
								.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Minor oil seep from rear output shaft on front diff ?						Suspension			1
Minor on se	ep nom rear output sha					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories	1		T
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u> Trim panel on right side of centre consul, down by clutch pedal is missing.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						_			
Inspected by: Jason Young Date: 05 Mar 2018									
I have read and understood this condition guide. Name:									