

Report ID: 17,374,668 Version: 1 Created: 02 Mar 2018

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:	KTW195	Reg Expiry:	15 Aug 2018	Engine	I	L	L
WoF Expiry:	30 Aug 2018	Odometer:	109,039 Kms	Good No:	17374668	Oil level	~		
VIN:	7AT0GF09X16007830	Next Service:	112517	Service Histor		Smoke & fumes	v		
						Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:	SC	-0	s sc sc		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission	V		
D = dent						Operation			<u> </u>
						Noise	~ ~		
PT = paint def C = crack	ect			+	SC	Clutch			
P = pin dent	Ho						~		
* = decals	s sc db					CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	3	3	mm
						Right front	3	3	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	4	1	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Pood Conditions During Test Driver						Central locking	2		
Road Conditions During Test Drive: Wet						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Yes Kms: 105,000						Reversing camera	~		
	•				-,		•		<u> </u>
Inspected by: Donovan Matara Date: 02 Mar 2018									
I have read and understood this condition guide. Name:									