

Basic Vehicle Condition Guide

Report ID: 17,374,827


Version: 2

Created: 22 Jun 2018

Make: Model: Suzuki Kizashi **Body Style:** Sedan Year: 2,010 Registration: FHW789 Reg Expiry: 06 Jul 2018 **WoF Expiry: Odometer:** 14 Mar 2019 **Good No:** 17374827 74,129 Kms VIN: JSAFRE91S00100095 **Next Service: Service History:** 81,741kms Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young Date: 15 Mar 2018

Name:

| | D | F-:1 | L NI/A | |
|------------------------------|--|---------|---------|--|
| Engine | Pass | Fail | N/A | |
| Oil level | | | | |
| Smoke & fumes | 1/ | | | |
| Performance | <i>V V</i> | | | |
| Noise | 1 | | | |
| Cooling System | | | | |
| Coolant condition | | | Ι | |
| Performance | 1/ | | | |
| Radiator / Hoses (visual) | <i>V</i> | | | |
| Transmission | | | | |
| Operation | · · | | | |
| Noise | \(\times \) \(\t | | | |
| Clutch | <i>y</i> | | | |
| CV joints | <i>v</i> | | | |
| Wheel bearings | <i>y</i> | | | |
| Brakes | | | | |
| Performance | V | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | · · | .2 | mm | |
| Right front | 6.0 | | mm | |
| Left rear | 2.8 | | mm | |
| Right rear | 4.0 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | ı | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | V V V V V | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | | | | |
| Rear view mirrors | v | | | |
| Radio (basic test only) | | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |
| | | | | |

Signature: