

Report ID: 17,376,840 Version: 1 Created: 09 Mar 2018

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2,012	Registration:	GHS248	Reg Expiry:	26 Jul 2018	Engine	I		1
WoF Expiry:		Odometer:	121,621 Kms	Good No:	17376840	Oil level	~		
VIN:	MR0EZ12G804155322	Next Service:	unknown	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta hava nat	la a constanti a di c	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and the	his can be arranged fo	or an additional o	harge.	Coolant condition	~		<u> </u>
		_				Performance	~		
Key:	SD	-0	W SP	-161-	SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S D SC			10-	SD SD	Operation	~		
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack					SC	Clutch	~		
P = pin dent						CV joints			~
* = decals	sc 916				ELIP SD	Wheel bearings	~		
SC = stone chi		20		1al		Brakes	•		
W = significant scuffs W SP SP PT P						Performance			1
		Note: som	ne defects & blemishes	may not be disr		Hand Brake	~		
	pection Comments	1010.3011	le delects à blemistie	s may not be disp	ayed in the diagram		•	ofture	
Grille badge missing.						Tyres (lowest observed tread depth of tyres) Left front 6			
							6		mm
						Right front Left rear	6		mm
							4		mm
Conditions During Body Inspection: Dry						Right rear 3 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Ok, dry .	inage a onder bor	ince inspectie	<u>Comments</u>			Suspension			1
OK, UIY.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation			
Average						Electrical / Accessories			
Seats	/					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	Average					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		
Ganaral						Window winder FR	~		<u> </u>
General Comments Good driving 2WD d/cab ute.						Window winder RL	~		<u> </u>
	יש ביידם ט/כמט טופ.					Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						Deta: 00.14- 22	10		
Inspecte	d by: Daryll Timms					Date: 09 Mar 20	10		

I have read and understood this condition guide.

Name:

Signature: