

Basic Vehicle Condition Guide

Report ID: 17,381,625


Version:

Created: 19 Mar 2018

Make: Model: Ford **Body Style:** Utility Ranger Year: 2,013 Registration: HED745 Reg Expiry: 27 May 2018 WoF Expiry: **Odometer:** 25 Nov 2018 **Good No:** 17381625 203,631 Kms VIN: MNAUMFF50DW2257 **Next Service: Service History:** 209,093kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak coming from right side of engine.

<u>Interior Comments</u>			
Seats	Average		
Carpets	Good		
Panels	Average		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young Date: 16 Mar 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	!	
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front 8.0 mr			
Right front	8.4		mm
Left rear	5.2		mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		!	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	\(\triangle \tr		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	-	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~
			-

Signature: