

Basic Vehicle Condition Guide

Report ID: 17,382,392


Version:

Created: 23 Mar 2018

Make: Model: Subaru **Body Style:** Wagon Legacy Year: 2,009 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 02 Mar 2019 73,160 Kms 17382392 VIN: 7AT0GF0BX18006446 **Next Service:** 83200 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No

Kms:

Inspected by: John Lindsay Date: 23 Mar 2018

Name:

	Pass	Fail	N/A		
Engine	ı				
Oil level	~				
Smoke & fumes	~				
Performance	\(\times \)				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	V				
Radiator / Hoses (visual)	~				
Transmission	•		•		
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes	•	•			
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread	d depth	of tyre	es)		
Left front	(5	mm		
Right front	(5	mm		
Left rear	6		mm		
Right rear	6		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	<i>V</i>				
Shock absorbers	~				
Air Conditioning / Heater					
Operation 🗸					
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	V V V V V				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	l				
Rear view mirrors	\(\triangle \)				
Radio (basic test only)					
CD (basic test only)	~				
Number of keys	2				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera			'		

Signature: