

Report ID: 17,382,699 Version: 1 Created: 04 Apr 2018

Make:	Hyundai	Model:	H1	Body Style:	Van		Pass	Fail	N/A
Year:	2,012	Registration:	GGZ887	Reg Expiry:	13 Dec 2018	Engine			
	2,012 01 Apr 2018	Odometer:	92,069 Kms	Good No:	17382699	Oil level	~		
VIN:	KMFWBX7JLCU44134		96.000kms	Service History		Smoke & fumes	~		
			50,000 kms		105	Performance	~		
	port is not a warranty		<i>с</i> н.н.			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	sc	-0	SP SP		S D	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO		10F	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Transmission	v		
D = dent	s dla			1n-	ED sw	Operation	~		
R = rust				10	1HH	Noise	~		
PT = paint def C = crack					SC	Clutch	~		
P = pin dent					JUII —	CV joints	•		~
* = decals	s sc PIP			AL-	ELP SP	Wheel bearings	~		
SC = stone chi	7	LO		A	& <u> </u>	Brakes	V		
W = significant scuffs SP W SD SP W S						Performance	~		T
			le defects & blemishes			Hand Brake	~		
	pection Comments	10000.3011	le delects & blemisnes	may not be disp	ayed in the diagram		•	ofturo	
L/R mudflap missing. Fuel cap dented.						Tyres (lowest observed tread depth of tyres)			
Stone chips on screen.						Left front	5		mm
						Right front	6		mm
						Left rear	3		mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
OK, dry.	inage a onder bor	ince inspectie	<u>in comments</u>			Suspension Suspension performance			
						· · ·	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			
rip on drivers seat						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		-
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		<u> </u>
<u>General Comments</u> Nice driving van.						Window winder RL			~
	vitch broken.					Window winder RR			~
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Con	ditions During Test	Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ning Mechanism:	Timing (Remote locking	~		<u> </u>
-	of Cam Belt Replac			Kms:		Sat. Nav. (basic test only)			~
Lvidence		ement. N	lot Applicable	NIT15.		Reversing camera			~
Inspected by: Daryll Timms Date: 04 Apr 2018									
	, , .,					······			

I have read and understood this condition guide.

Name:

Signature: