

Report ID: 17,395,720 Version: 1 29 Mar 2018 Created:

Make:	Mazda	Model:	CX-5	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	<b>Registration:</b>	HKL317	Reg Expiry:	18 May 2018	Engine	1		
WoF Expiry:	04 Apr 2019	Odometer:	102,746 Kms	Good No:	17395720	Oil level	~		
VIN:	JM0KE107100250621	Next Service:	104000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S D SC					Performance	~		
Key:	ISDSC IL	$-\infty$	S SC S SC		S P SC	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SDSC 999 SSC						Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs						Performance 🖌			
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Minor spider put on the spot						Tyres (lowest observed tread	served tread depth of tyres)		
Minor spider rust on the roof ,						Left front		7	mm
						Right front		7	mm
						Left rear		, 7	mm
Conditions During Body Inspection: Dry						Right rear		7 mm	
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		L
						Operation	~		
Interior Comments						Electrical / Accessories	•		L
Seats	Good					Head lights	~		
	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		$\left  - \right $
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General</u> (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		<u> </u>
Read Conditions During Test Drives						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
		· .							
Inspected by: Donovan Matara Date: 29 Mar 2018									
I have read and understood this condition guide. Name:									