

# **Basic Vehicle Condition Guide**

Report ID: 17,396,908

Pass

Version: 1

Created: 27 Mar 2018


Fail

N/A

Make: Model: **Great Wall** V-Series **Body Style:** Utility Year: Registration: HWB582 Reg Expiry: 2,014 22 Mar 2018 WoF Expiry: **Odometer:** 19 Mar 2019 **Good No:** 17396908 151,000 Kms VIN: LGWDBE179EB623835 Next Service: 160000 **Service History:** 

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



#### **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Missing centre cap of wheel, back left side flare unstuck, chrome coming off driver side door handle.

Conditions During Body Inspection: Wet

### **Under Carriage & Under Bonnet Inspection Comments**

No underbody inspection

| Interior Comments |                         |  |  |
|-------------------|-------------------------|--|--|
| Seats             | small tear in back seat |  |  |
| Carpets           | smoke burns in carpet   |  |  |
| Panels            | Good                    |  |  |
| Dashboard         | Good                    |  |  |

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Jamie Cook

Evidence of Cam Belt Replacement: No

Kms:

| Engine                       |                                       |         |    |
|------------------------------|---------------------------------------|---------|----|
| Oil level                    | ~                                     |         |    |
| Smoke & fumes                | \( \times \)                          |         |    |
| Performance                  | ~                                     |         |    |
| Noise                        | ~                                     |         |    |
| Cooling System               |                                       | •       |    |
| Coolant condition            | ~                                     |         |    |
| Performance                  | ~                                     |         |    |
| Radiator / Hoses (visual)    | ~                                     |         |    |
| Transmission                 | •                                     | !       |    |
| Operation                    | ~                                     |         |    |
| Noise                        | \( \times \)                          |         |    |
| Clutch                       | ~                                     |         |    |
| CV joints                    | ~                                     |         |    |
| Wheel bearings               | ~                                     |         |    |
| Brakes                       |                                       |         |    |
| Performance                  | ~                                     |         |    |
| Hand Brake                   | ~                                     |         |    |
| Tyres (lowest observed tread | depth                                 | of tyre | s) |
| Left front                   | 6                                     | .7      | mm |
| Right front                  | 6                                     |         | mm |
| Left rear                    | 8.7                                   |         | mm |
| Right rear                   | 7.8                                   |         | mm |
| Spare                        |                                       | Yes     |    |
| Suspension                   | •                                     |         |    |
| Suspension performance       | ~                                     |         |    |
| Steering performance         | ~                                     |         |    |
| Shock absorbers              | ~                                     |         |    |
| Air Conditioning / Heater    |                                       |         |    |
| Operation                    | ~                                     |         |    |
| Electrical / Accessories     | •                                     | •       | •  |
| Head lights                  | ~                                     |         |    |
| Tail lights                  | ~                                     |         |    |
| Indicators                   | ~                                     |         |    |
| Dashboard warning lights     | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |         |    |
| Wipers (front & rear)        | ~                                     |         |    |
| Window winder FL             | ~                                     |         |    |
| Window winder FR             | ~                                     |         |    |
| Window winder RL             | ~                                     |         |    |
| Window winder RR             | <b>V</b>                              |         |    |
| Rear view mirrors            | <b>V</b>                              |         |    |
| Radio (basic test only)      | ~                                     |         |    |
| CD (basic test only)         | ~                                     |         |    |
| Number of keys               | 1                                     |         |    |
| Central locking              | ~                                     |         |    |
| Remote locking               | ~                                     |         |    |
| Sat. Nav. (basic test only)  |                                       |         | ~  |
| Reversing camera             |                                       |         | ~  |

I have read and understood this condition guide.

Name: .....

Signature: .....

27 Mar 2018