

Basic Vehicle Condition Guide

Report ID: 17,401,044


Version:

Created: 21 Mar 2018

Make: Model: Mazda Familia **Body Style:** Sedan Year: 1,994 Registration: AGR373 Reg Expiry: 16 Jul 2018 **Odometer:** WoF Expiry: **Good No:** 17401044 11 May 2018 165,433 Kms VIN: 7A8C10H0701419932 **Next Service: Service History:** due No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip on front windscreen

Window washer and wiper blade needs attention

L/F tyre needs replacing(outter wear)

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Brake fluid low Engine oil leak Battery not secured

| <u>Interior Comments</u> | | |
|--------------------------|------|--|
| Seats | Good | |
| | Good | |

| • | Carpets | Good |
|---|-----------|------|
| | Panels | Good |
| | Dashboard | Good |

General Comments

Inspected by:

Driver seat needs attention Air corn not working **Engine** noisy No engine oil

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Rahul Singh

Evidence of Cam Belt Replacement: Kms: No

Name:

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|---------|
| Engine | | | • |
| Oil level | | ~ | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | | ~ | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ' | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | es) |
| Left front | | 2 | mm |
| Right front | | | mm |
| Left rear | | 1 | mm |
| Right rear | | 1 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | | ~ | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | | ~ | |
| Window winder FL | ~ | | |
| Window winder FR | | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | 1 | |
| Central locking | ~ | | |
| Remote locking | | | ~ |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |

21 Mar 2018

Signature:

Date: