

Report ID: 17,401,194


Version:

Created: 13 Apr 2018

| Make:       | Volkswagen       | Model:        | Tiguan     | Body Style:     | SUV          |
|-------------|------------------|---------------|------------|-----------------|--------------|
| Year:       | 2,014            | Registration: | HGW539     | Reg Expiry:     | 27 Aug 2018  |
| WoF Expiry: | 29 Mar 2018      | Odometer:     | 91,392 Kms | Good No:        | 17401194     |
| VIN:        | WVGZZZ5NZEW04912 | Next Service: | 92671      | Service History | <b>y:</b> No |

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Dirty

| Interior Comments |      |  |  |  |
|-------------------|------|--|--|--|
| Seats             | Good |  |  |  |
| Carpets           | Good |  |  |  |
| Panels            | Good |  |  |  |
| Dashboard         | Good |  |  |  |

## **General Comments**

Drives well

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Kms: Not Applicable

13 Apr 2018 Inspected by: Stuart Melbourne Date:

Name: .....

| ~     |  |     |
|-------|--|-----|
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
|       |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| •     |  |     |
| ~     |  |     |
| ~     |  |     |
|       |  | ~   |
| ~     |  |     |
| ~     |  |     |
|       |  | •   |
| ~     |  |     |
| ~     |  |     |
| depth | of tyre                                | es) |
| 3     | 3                                      | mm  |
| 3     | 3                                      | mm  |
| 7     | 7                                      | mm  |
| 7     | 7                                      | mm  |
|       | Yes                                    |     |
|       |  |     |
| >     |  |     |
| ~     |  |     |
| ~     |  |     |
|       |  |     |
| ~     |  |     |
|       |  |     |
| ~     |  |     |
| >     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| ~     |  |     |
| 2     |  |     |
| ~     |  |     |
| ~     |  |     |
|       |  | ~   |
|       |  | V   |
|       | マンマンマンマンマンマンマンマンマンマンマンマンマンマンマンマンマンマンマン |     |

Signature: .....