

Report ID: 17,403,561 Version: 2 Created: 04 May 2018

Make:	Mitsubishi	Model:	Pajero	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,996	Registration:	CPB201	Reg Expiry:	21 Jul 2018	Engine	1		
WoF Expiry:	14 Jun 2018	Odometer:	288,378 Kms	Good No:	17403561	Oil level	~		
VIN:	7A8CJ08070521290	8 Next Service:	294390	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	W U	-0	w w		w	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC A A A A A A A A A A A A A A A A A A						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 99						Wheel bearings		~	
SC = stone chips						Brakes			
W = significant scuffs W W W S						Performance	~		
Rody Inspection Commonts Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		~	
Body Inspection Comments Tyres edge/middle wearing						Tyres (lowest observed tread depth of tyres)			
The edge/mode wearing						Left front 0.0 m			mm
						Right front	-	.0	mm
						Left rear	0.0		mm
Conditions During Body Inspection: Dry						Right rear			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear sway bar bushes and link play.						Suspension performance	~		
Front sway bar bush play. Front brakes low.						Steering performance	~		
Oil leaks.						Shock absorbers	~		
Wheel bearing play in R/F.						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Seats Average					Head lights	~		
	Average	2				Tail lights	~		
Carpets	, trendge	-				Indicators	~		
Panels	Average	2				Dashboard warning lights	~		
	Average	2				Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Handbrake travel.						Window winder RR	~		
Knock in suspension. Requires wheel alignment. Steering wheel not stright.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Dion Mair Date: 21 Mar 2018									

I have read and understood this condition guide.

Name:

Signature: