

Basic Vehicle Condition Guide

Report ID: 17,405,389


Version: 2

Created: 10 Apr 2018

Make: Model: Nissan **Body Style:** Sedan Teana Year: 2,006 Registration: Reg Expiry: HBQ636 12 Mar 2018 WoF Expiry: **Odometer:** 31 Mar 2019 **Good No:** 17405389 115,978 Kms VIN: 7AT0DH71X13204913 **Next Service: Service History:** 116000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Front bumper misaligned

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Alarm remote needs attention

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Xinghui Lin Date: 10 Apr 2018

Name:

	Pass	Fail	N/A
Engine	-		
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			1
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	1		!
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front	T		mm
Right front	5		mm
Left rear	6		mm
Right rear	6		mm
Spare	<u> </u>	Yes	
 Suspension		103	
Suspension performance	~		
Steering performance	~		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	\(\times \)		
Dashboard warning lights	1/		
Wipers (front & rear)	<i>y</i>		
Window winder FL	~		
Window winder FR	~		
Window winder RL			
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	<i>V</i>		
CD (basic test only) Number of keys	1		
	1		
Central locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Domata lacking		1	
Remote locking	-		
Remote locking Sat. Nav. (basic test only) Reversing camera			~

Signature: