

Report ID: 17,407,212 Version: 1 25 Mar 2018 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2,016	Registration:	KBG764	Reg Expiry:	30 Apr 2018	Engine			
WoF Expiry:	2,010	Odometer:	53,899 Kms	Good No:	17407212	Oil level	~		
VIN:	KL3CD2659GB534135	Next Service:	55,000 Kills	Service Histor		Smoke & fumes	~		
	RESCO2057GD554155				. 103	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Performance	~		
Key:	sc	-0	sc sc			Radiator / Hoses (visual)	~		
S = scratch	Sec	20		10/2	\sim	Transmission	~		
D = dent	s sc			1 - L	EID IS				
R = rust				10		Operation Noise	~		
PT = paint defe C = crack	ect			+		Clutch	~		
C = Crack P = pin dent	Ho								~
* = decals	sc pp				ANR -	CV joints Wheel bearings	~		
SC = stone chips									
W = significant scuffs SC S						Brakes			
		Nata				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake			<u> </u>
					Tyres (lowest observed tread depth of tyres)				
						Left front	6		mm
						Right front	6		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriege & Under Despetien Comments					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Drives well						Window winder RR	~		-
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
	_		-			Remote locking	~		
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Stuart Melbourne Date: 25 Mar 2018									

I have read and understood this condition guide.

Name:

Signature: