

## **Basic Vehicle Condition Guide**

Report ID: 17,408,184

**Pass** 

~

~

/

V

1

/

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 27 Mar 2018

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

~

5

6

6

1

/

/

1

/

1

1


2

Yes

Make: Model: **Body Style:** Ford **Transit** Van Year: Registration: **Reg Expiry:** 2,014 HFQ405 21 Apr 2018 WoF Expiry: **Odometer: Good No:** 17408184 22 Jan 2018 74,582 Kms VIN: WF0XXXTTFXDC62522 **Next Service: Service History:** 101,000kms Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

R/H tail light cracked. Chipped screen.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

OK, dry.

Interior Comments		
Seats	Average	
Carpets	hole on drivers side .	
Panels	Average	
Dashboard	Average	

## **General Comments**

Good driving big van.

Inspected by:

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

**Daryll Timms** 

I have read and understood this condition guide.

**Evidence of Cam Belt Replacement:** No

	Remote locking			
	Sat. Nav. (basic test only)		~	
Kms:	Reversing camera	~		
Date: 27 Mar 2018				
Name: Signature:				