

Report ID: 17,411,620 Version: 1 Created: 27 Mar 2018

Make:	Hyundai	Model:	Santa FE	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2,002	Registration:	CHM667	Reg Expiry:	31 Oct 2018	Engine				
	17 Aug 2018	Odometer:	187,897 Kms	Good No:	17411620	Oil level	~			
VIN:	KMHSC81DR2U24199	Next Service:	190000	Service Histor		Smoke & fumes	~			
	10113001012024133		190000		. 110	Performance	~			
	port is not a warranty					Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	S P SC	-0	S SC S P SC		s sc	Radiator / Hoses (visual)	~			
S = scratch	STO	A CO		10c	T	Transmission	v			
D = dent	s c sc			1 - L	ED SD	Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint def C = crack				+	S SC	Clutch			~	
P = pin dent	Htc				JUII —		~		~	
* = decals	s sc pp			AL-	ELIPS	CV joints	-			
SC = stone chi	ps US	LA		A		Wheel bearings	~			
W = significant scuffs S SC S D SC S D SC S D SC						Brakes				
	3.30	N				Performance	~			
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
						Left front		5	mm	
						Right front	:	5 mm		
						Left rear	2 mm			
Conditions During Body Inspection: Dry						Right rear	3 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes			
<u>Under Ca</u>	rriage & Under Bor	inet inspectio	on Comments			Suspension				
						Suspension performance	~			
						Steering performance	~			
Shock absorbers							~			
						Air Conditioning / Heater				
						Operation		~		
Interior Comments						Electrical / Accessories				
Seats	drivers sea	it ripped ,				Head lights	~			
Comoto	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	middle co	nsole lid broken	,			Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)		~		
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking										
			ыу			Remote locking	~			
Engine Ti	ming Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Donovan Matara Date: 27 Mar 2018										

I have read and understood this condition guide.

Name:

Signature: