

Report ID: 17,414,880 Version: 2 14 Aug 2018 Created:

Make:	Nissan	Model:	Maxima	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2,002	Registration:	BAM762	Reg Expiry:	11 Aug 2018	Engine	I		L	
WoF Expiry:	31 Jan 2019	Odometer:	199,446 Kms	Good No:	17414880	Oil level	~			
VIN:	JN1CCUA33A0110908	Next Service:	206000	Service History	/: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~			
Key:	SC	-0	SC S P	-01-	S SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	sscw bla			The	SDW	Operation	~			
R = rust PT = paint def				$\prod$		Noise	~			
C = crack				$+ \mathbf{\nabla}$	╫╫┼───	Clutch	•		~	
P = pin dent						CV joints	~			
* = decals	PSC 916			The	ETT SPT	Wheel bearings	~			
SC = stone chips						Brakes				
W = significan	t scuffs SC W	$- \emptyset$	S SDSC		S D SC	Performance	~			
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~			
·	pection Comments					Tyres (lowest observed tread	•	of tyre		
Stonechips on windscreen. Front number plate mount damaged. Headlamps need buffing. Light in LF door card missing. Wear on RF seat and seatbelt. Wear on RF door card.									 	
g	2001 cara					Right front	5		mm	
						Left rear	3		mm	
						Right rear	3		-	
Conditions During Body Inspection: Dry						Spare	7 mm			
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes			
	r missing on engine. En			worn		Suspension performance				
	r missing on engine. En	gine has on seep				Steering performance	<b>v</b>		-	
						Shock absorbers	~ ~			
						Air Conditioning / Heater	V			
Interior Comments						Operation   Electrical / Accessories				
Average						Head lights				
Seats							~			
Carpets	Average					Tail lights	~			
	Average					Indicators	~			
Panels						Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~		<b> </b>	
						Window winder FL	~			
General (	omments					Window winder FR	~			
General Comments Fuel gauge not reading correctly.					Window winder RL	~		<u> </u>		
						Window winder RR	~			
Drives ok.						Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~			
						CD (basic test only)	~			
L						Number of keys	1			
Road Con	ditions During Test	Drive:	Dry			Central locking	~			
Engine Ti	ning Mechanism	<b>T</b> :				Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Evidence	or cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Roger King Date: 14 Aug 2018										

Name: .....

Signature: .....