

Basic Vehicle Condition Guide

Report ID: 17,416,369


Version: 5

Created: 08 Aug 2018

Make: Model: Mazda CX-5 **Body Style:** SUV Year: 2,016 Registration: KDU659 Reg Expiry: 30 Oct 2018 **WoF Expiry: Odometer:** 31 Oct 2019 **Good No:** 17416369 44,156 Kms VIN: JM0KE107200399633 **Next Service: Service History:** 54,153 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese Date: 08 Aug 2018

Name:

	Pass	Fail	N/A
Engine	1 433	Tun	14//
Oil level	·/		
Smoke & fumes	\(\triangle \)		
Performance	<i>y</i>		
Noise	<i>y</i>		
Cooling System			
Coolant condition	·/		
Performance	V		
Radiator / Hoses (visual)	•		
Transmission			
Operation	·/		
Noise	•		
Clutch			
CV joints			
Wheel bearings			
Brakes	<i>V</i>		
Performance			
Hand Brake			
	d donth	of ture)
Tyres (lowest observed tread Left front			
	7		mm
Right front Left rear	7		mm
	7		mm
Right rear	7		mm
Spare Suspension		Yes	
Suspension performance			
Steering performance			
Shock absorbers	V		
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights	.,		
Tail lights	•		
Indicators	· ·		
Dashboard warning lights	<i>y</i>		
Wipers (front & rear)	V V V V V V V V V V V V V V V V V V V		
Window winder FL	·		
Window winder FR	<i>y</i>		
Window winder RL	<i>y</i>		
Window winder RR	<i>y</i>		
Rear view mirrors	<i>'</i>		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys			
Central locking	2		
Remote locking			
Sat. Nav. (basic test only)	\(\sigma \)		
Reversing camera	~		
			1

Signature: