

Report ID: 17,416,503 Version: 2 24 Jan 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016 Registration: KBD696 Reg Expiry: 18 Feb 2019				Engine				
WoF Expiry:	16 Nov 2019	Odometer:	39,273 Kms	Good No:	17416503	Oil level	~		
VIN:	6G1PD6EMXGL24012	Next Service:	unknown	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	L	-0	sc sc	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			TIN	HIL S	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc 916		<u> </u>	- AL	ETP w	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: con	ne defects & blamisbas		laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								ofture))
Stone chips on screen .						Tyres (lowest observed tread depth of tyres)			
						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear 5.0 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	metinspectio	<u>on comments</u>			Suspension		1	1
Tidy and dr	у.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Caract	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Nice hatch,	drives well.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•								-
Inspected by: Daryll Timms Date: 29 Mar 2018									

I have read and understood this condition guide.

Name: