

Report ID: 17,417,726 Version: 4 Created: 24 Jul 2018

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HKY887	Reg Expiry:	22 May 2018	Engine			
WoF Expiry:		Odometer:	195,985 Kms	Good No:	17417726	Oil level	~		
VIN:	JF2BRMKC5EG063930	Next Service:	200,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	sc	-0		-161-	W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S C SC W D D S D C W						Operation 🖌			
R = rust PT = paint defect						Noise	~		
C = crack					SC	Clutch			~
P = pin dent					ᅰЦ	CV joints	~		•
*=decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W P W W S						Performance	~		
		Note: son	ne defects & blemishes	may not be disc	blaved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed treat		oftvre	() ()
Cracks in the paint front and rear bumper.						Left front 4 mm			
						Right front			mm
						Left rear		5	mm
Canalitian	- Dunin - Dadu Ina		_			Right rear		1	mm
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Mold on left front seat belt						Head lights			
						Tail lights	~		
Carpets	Good					Indicators	~		
Davida	Good					Dashboard warning lights			
Panels						Wipers (front & rear)	~ ~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
Read Canditions Duving Test Driver						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	<i>v</i> <i>v</i>		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	<i>v</i> <i>v</i>		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	<i>v</i> <i>v</i>		
Inspected by: Bobby Zhong Date: 24 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: