

Report ID: 17,419,111 Version: 2 Created: 12 Apr 2018

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,003	Registration:	FFF616	Reg Expiry:	31 Aug 2018	Engine			
WoF Expiry:	02 Mar 2019	Odometer:	201,452 Kms	Good No:	17419111	Oil level	~		
VIN:	7A8C1390709103942	Next Service:	201000	Service Histor	-	Smoke & fumes	~		
						Performance	v		
	port is not a warranty		C 1 1	D		Noise	v		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	sc	-0	D SC SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation V			
						Noise	~		
PT = paint def C = crack	ect M			+		Clutch	V		
P = pin dent	LHC								~
* = decals	PT DE			SI	Ell'As	CV joints	~		
SC = stone chips						Wheel bearings	5		
W = significant scuffs S S S S S SC						Brakes			1
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Wiper mark and stone chips front screen.						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front	6	5	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Poor					Tail lights	~		
Carpets	roor					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
<u>General</u> (<u>Comments</u>					Window winder RL	~		
Runs well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	-		
						Number of keys	/		
						-	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Timing (Thain			Remote locking		~	
-	of Cam Belt Replac			Kms:		Sat. Nav. (basic test only)			~
	or carri bert nepide		lot Applicable	11113.		Reversing camera	~		
Inspecte	d by: Brian Hill					Date: 12 Apr 20	18		

I have read and understood this condition guide.

Name:

Signature: