

Report ID: 17,420,116 Version: 1 Created: 20 Apr 2018

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2,013	Registration:	GTY59	Reg Expiry:	16 Oct 2018	Engine	I	I	L
	11 Apr 2019	Odometer:	117,834 Kms	Good No:	17420116	Oil level	~		
VIN:	MR0FZ22G201190739	Next Service:	126,000	Service Histor		Smoke & fumes	v		
			.20,000		,	Performance	~		
	port is not a warranty		f	Danta harra nat		Noise	v		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	sc	-0	W SW		SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent D = runt SSCW						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent						CV joints	~		
*=decals SC QQ						Wheel bearings			
SC = stone chips						Brakes	~		
W = significant scuffs SC SC SC W SC W SC W SC W						Performance			1
							v		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Stone chips on windscreen.						Tyres (lowest observed tread	· ·	,	
						Left front		1	mm
						Right front			mm
						Left rear		4	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Good Good						Electrical / Accessories		1	
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
		• •							
Inspected by: Donovan Matara Date: 20 Apr 2018									
I have read and understood this condition guide. Name:									