

Report ID: 17,420,128 Version: 2 Created: 14 May 2018

Make:	Toyota	Model:	Landcruiser Prado	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HMA766	Reg Expiry:	05 Jun 2018	Engine	1		L
WoF Expiry:	06 Jun 2018	Odometer:	124,617 Kms	Good No:	17420128	Oil level	~		
VIN:	JTEBH3FJ10K134938	Next Service:	136691	Service Histor		Smoke & fumes	~		<u> </u>
						Performance	~		<u> </u>
	port is not a warranty		for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S P SC S P SC		S SC	Radiator / Hoses (visual)	~		
S = scratch	ATE.	A U		NG G	Tan	Transmission			1
D = dent R = rust	s bla			715	S SC	Operation	~		
R = rust PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch	-		~
P = pin dent					7414	CV joints	~		
* = decals	ssc 916			- No	ELLES	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs S SC		S S		S SC	Performance	~		
Dedulmen		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body inst	pection Comments					Tyres (lowest observed tread	d depth	of tyre	1 2s)
									mm
						Right front	-		mm
						Left rear		, 1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	drivers sea	at small rip,wear	n tear ,			Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	Average					Indicators	~		1
Panels	Average					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		<u> </u>
Dashboa	rd Average					Window winder FL	~		<u> </u>
	I					Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		1
						CD (basic test only)	~		<u> </u>
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	~		
			у			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms:   Reversing camera							~		
Inspected by: Donovan Matara Date: 14 May 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....