

Turners Certified Imports 50 Point Check

Report ID: 17,420,515

Version: 3

Created: 05 Oct 2018

Date: 05 Oct 2018

Signature:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED diagramment with the control of the contr	nostic testing undertaken. The vehedited inspection agency and been to	iicle has undergone a thorough co est driven up to 50km/h from cold.	ompliance check by an NZTA
Model: Regius	Body Style: People Mover Odometer: 92,919 Kms VIN: 7AT0H63TX18107219 nnet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Cambelt No Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4 mm
Head lights	Noise	Smoke & fumes	Right front 5 mm
Tail lights	Clutch	Performance	Left rear 1.6 mm
Indicators	CV joints •	Noise	Right rear 1.6 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake	Suspension	Heater fan
Window winder RR	Kova 9 Loshina		Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	Turners Cartified Voy
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

Inspected by: Jason Law

Number of keys

Reversing camera