

Report ID: 17,421,724 Version: 2 23 Jul 2018 Created:

Make:	Audi	Model:	A5	Body Style:	Sports Car		Pa	is Fai	I N/A	
Year:	2,008	<b>Registration:</b>	LGJ768	Reg Expiry:	07 Jan 2019	Engine				
WoF Expiry:	09 Feb 2019	Odometer:	127,349 Kms	Good No:	17421724	Oil level	~			
VIN:	WAUZZZ8T78A03169	Next Service:	134,000	Service Histor	<b>y:</b> No	Smoke & fumes	· /			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System	Cooling System			
a fuil mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant conditi	ion 🖌			
	S W		C C		S D	Performance	<ul> <li>✓</li> </ul>			
Key: S VV S S S D						Radiator / Hose	s (visual) 🖌			
						Transmission	<b>!</b>			
D = dent     R = rust     PT = paint defect     C = crack						Operation	<b>v</b>			
						Noise	~			
						Clutch			~	
P = pin dent						CV joints	~			
* = decals S SC = stone chips						Wheel bearings	5 🖌			
W = significant scuffs						Brakes				
						Performance 🗸				
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~			
Driver's sunshade clip broken						Tyres (lowest observed tread depth of tyres)				
						Left front	Left front 5		mm	
						Right front 6		6	mm	
						Left rear	Left rear 6		mm	
Conditions During Body Inspection: Dry						Right rear 6 m		mm		
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Engine oil leak Marks of coolant leak around thermostat housing						Suspension per				
Transmission oil leak						Steering perfor	· ·			
Rear RH drive shaft oil leak						Shock absorber	rs 🖌			
						Air Conditioning / Heater				
Interior (	omments					Operation	~			
Interior Comments Average						Electrical / Accessories				
Seats	//veluge					Head lights	~			
Carpets	Average					Tail lights	<ul> <li>✓</li> </ul>			
· · ·	Average			Indicators	✓		_			
Panels	/ Weidge					Dashboard war	5 5			
Dashboa	rd Good					Wipers (front &		~		
						Window winde				
General (	omments					Window winde				
General Comments Noise while starting, transmission mounting needs attention						Window winde			~	
Engine tapping noise						Window winde			~	
						Rear view mirro				
						Radio (basic tes				
						CD (basic test o				
						Number of keys 2				
Road Conditions During Test Drive: Dry						Central locking			_	
Engine Timing Mechanism: Timing Chain						Remote locking				
							test only)		~	
			lot Applicable			Reversing came	era		~	
Inspected by: Bobby Zhong Date: 23 Jul 2018										

I have read and understood this condition guide.

Name: .....

Signature: .....