

Basic Vehicle Condition Guide

Report ID: 17,422,010

Version: 3

Engine

Oil level

Created: 10 Jul 2018

Pass


N/A

Fail

Make: Model: **Body Style:** Honda Odyssey People Mover Year: 2,003 Registration: Reg Expiry: LEF944 03 Jul 2018 WoF Expiry: **Odometer: Good No:** 17422010 18 Apr 2019 122,641 Kms VIN: **Next Service: Service History:** JHMRA68502C201970 132,635kms No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on front windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak from around engine sump pan area.

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Left rear door power window not working & has been taped up. Key remote not working to lock & unlock vehicle. Cam belt has been replaced, but cannot read label as writing has worn off it.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** Kms: Yes

Inspected by: Date: 09 Apr 2018 Jason Young

Name:

| Smoke & fumes | ' | | |
|------------------------------|--------------|----------|----------|
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | \(\times \) | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | 1 | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | 1 |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | l depth | n of tyr | es) |
| Left front | 6.6 mm | | |
| Right front | 6.5 | | mm |
| Left rear | 7.0 | | mm |
| Right rear | 7.0 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | 1 | 1 |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | T |
| Tail lights | ~ | | |
| Indicators | ~ | | 1 |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | v | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | ~ | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | <i>y</i> | | 1 |
| CD (basic test only) | ~ | | |
| Number of keys | | | |
| Central locking | 1 | | |
| Remote locking | _ | ., | |
| | | - | |
| Sat. Nav. (basic test only) | | | ' |
| Reversing camera | | | |

Signature: