

Report ID: 17,422,790 Version: 2 Created: 17 Sep 2018

Make:	Peugeot	Model:	207Sport	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	Registration:	HQU281	Reg Expiry:	07 Jul 2018	Engine			
WoF Expiry:	15 Oct 2018	Odometer:	94,832 Kms	Good No:	17422790	Oil level	~		
VIN:	VF3WC5FWF33766952	Next Service:	104000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	V		
Key:		-0	ls ls	-M-		Radiator / Hoses (visual)	V		
S = scratch						Transmission			1
D = dent R = rust	s dla			715	HILS	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	r		
C = crack						Clutch			~
P = pin dent	HD				ᅰ╽	CV joints	~		
* = decals	- 91E			- NL		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S						Performance	~		
Deskulas		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			L
								mm	
						Right front		3	mm
						Left rear		4	mm
Conditions During Rody Inspections					Right rear			mm	
Conditions During Body Inspection: Dry						Spare	4 r Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension Yes			
	•					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation		~	
Interior Comments						Electrical / Accessories		v	L
Seats	Good					Head lights	~		
Jeals						Tail lights	~		
Carpets	Good						~		
Develo	Good					Dashboard warning lights	~		$\left - \right $
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FL Window winder FR			
General (Comments					Window winder FR Window winder RL	v		
Key broken						Window winder RL Window winder RR	v		
A/C not get						Rear view mirrors	v		
							v		
						Radio (basic test only)	v		
						CD (basic test only) Number of keys	/		L
						· · · · · · · · · · · · · · · · · · ·	1		
Road Con	ditions During Test	: Drive:	Dry			Central locking	~		
Engine Tir	ning Mechanism:	Timing (- hain			Remote locking	~		
-	of Cam Belt Replac			Kms:		Sat. Nav. (basic test only)			~
	or cam bert nepiac	N	lot Applicable	11113.		Reversing camera			~
Inspected by: Donovan Matara Date: 17 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: