

Report ID: 17,426,944 Version: 1 Created: 02 Oct 2018

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A
Year:	2016	Registration:	KDA744	Reg Expiry:	01 May 2018	Engine	1	1	1
WoF Expiry:		Odometer:	54,825 Kms	Good No:	17426944	Oil level	~		
VIN:	6G1PE5EM4GL244991	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for any and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		-
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W D						Performance 🖌			
Note: come defecte % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments							•		
						Tyres (lowest observed tread depth of tyres) Left front 7 mm			
						Right front	,		mm
						Left rear			-
								7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meemspeede	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation	~		
Good						Electrical / Accessories	1		
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	9000					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		
Increast-	Data: 02 Oct 20	10							
Inspected by: John Lindsay Date: 02 Oct 2018									
I have read and understood this condition guide. Name:									