

Report ID: 17,429,601 Version: 1 Created: 13 Sep 2018

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2017	Registration:	КНҮ668	Reg Expiry:	01 May 2018	Engine			I	
WoF Expiry:		Odometer:	35,487 Kms	Good No:	17429601	Oil level	~			
VIN:	6G1PD6EM2GL24914(	Next Service:		Service Histor		Smoke & fumes	~			
						Performance	~			
	port is not a warranty	wation is mode	for one and miles as	Dauta hava nat	heen discontlad or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:		-0		-161-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	- GIE			The	EIII S	Operation	~			
R = rust PT = paint def				$\prod$		Noise	~			
C = crack				$+ \vee$		Clutch	-		~	
P = pin dent					세비	CV joints	~			
* = decals	s 916			The		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	of tyre	es)	
Stone chips front screen.								mm		
						Right front	6.		 mm	
						Left rear		.5 5	mm	
Condition	as During Pady Ins	action				Right rear		-	 mm	
Conditions During Body Inspection: Dry						Right rear 6 mm   Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
FWD.	-					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General (	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
Road Conditions During Test Drive: Dry						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~	
L	-								L *	
Inspecte	Inspected by: Eddie Marsters Date: 13 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....