

Report ID: 17,430,654 Version: 3 Created: 07 May 2018

Make:	Toyota	Model:	Passo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,004	Registration:	HKU867	Reg Expiry:	10 Apr 2018	Engine			
WoF Expiry:	04 May 2018	Odometer:	125,898 Kms	Good No:	17430654	Oil level	~		
VIN:	7AT0H650X14015884	Next Service:	132893	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0	SP	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			715	HILS	Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack				+		Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sc 916			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S						Performance	~		
Dedular		Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
								mm	
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wat						Right rear			mm
Conditions During Body Inspection: Wet						Right rear 4.0 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats stains						Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
Drives well						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Driver were						Central locking	2 V		
Road Conditions During Test Drive: Wet						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
		Į							•
Inspected by: Stuart Melbourne Date: 11 Apr 2018									

I have read and understood this condition guide.

Name:

Signature: