

Basic Vehicle Condition Guide

Report ID: 17,432,456

Pass

1

/

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 16 May 2018

Fail

N/A

1

mm

mm

mm

 mm

2

3

2

1

/

/

1

1


1

Yes

Make: Model: **Body Style:** Subaru Legacy Wagon Year: Registration: **Reg Expiry:** 2,006 WoF Expiry: **Odometer: Good No:** 09 Apr 2019 97,810 Kms 17432456 VIN: **Next Service: Service History:** 7AT0GF0BX18043689 107,788kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Clean & dry.

Interior Commen	<u>ts</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** Nο

Daryll Timms

I have read and understood this condition guide.

	Sat. Nav. (basic test only)	
Kms:	Reversing camera	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Date: 16 May 2018		
Name:	Signature:	