

Report ID: 17,483,456 Version: 1 18 Apr 2018 Created:

Make:	Holden	Model:	Astra	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,002	<b>Registration:</b>	LGR666	<b>Reg Expiry:</b>	26 Jul 2018	Engine			
WoF Expiry:	10 Oct 2018	Odometer:	216,613 Kms	Good No:	17483456	Oil level	~		
VIN:	W0L0TGF0825104300	Next Service:	223500	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S P SC	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	S SC	Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack				+	SC	Clutch	~		
P = pin dent						CV joints	~		
* = decals	S PT SC 916			The	EITR	Wheel bearings	· ·		
SC = stone chips						Brakes	•		<u> </u>
W = significant scuffs S SC S SC						Performance	~		
		Note: com			laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture	
Bonnet needs paint ,						Tyres (lowest observed tread depth of tyres			
						Left front	6		mm
						Right front		7	mm
[						Left rear		2	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	inet inspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpots	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	dash crack	ed ,				Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		·
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L								1	
Inspected by: Donovan Matara Date: 18 Apr 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....