


<b>Make:</b>	Holden	<b>Model:</b>	Barina	<b>Body Style:</b>	Hatchback
<b>Year:</b>	2,008	<b>Registration:</b>	HWB613	<b>Reg Expiry:</b>	21 Jul 2018
<b>WoF Expiry:</b>	11 Apr 2019	<b>Odometer:</b>	95,788 Kms	<b>Good No:</b>	17484938
<b>VIN:</b>	KL3SF08619B349639	<b>Next Service:</b>	99,000kms	<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments**

Stone chips on front windscreen.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Minor oil leak from rocker cover gasket.

**Interior Comments**

Seats	Good
Carpets	Good
Panels	Average
Dashboard	Good

**General Comments**

One of key remotes not working to lock & unlock vehicle.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	6.2	mm	
Right front	6.8	mm	
Left rear	7.8	mm	
Right rear	6.6	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 13 Apr 2018

I have read and understood this condition guide.

Name: .....

Signature: .....