

Basic Vehicle Condition Guide

Report ID: 17,487,673


Version: 2

Created: 30 Jul 2018

Make: Model: Nissan Skyline **Body Style:** Sedan Year: 2,007 Registration: KSB579 Reg Expiry: 19 Jul 2018 WoF Expiry: **Odometer: Good No:** 18 Jul 2018 17487673 83,753 Kms VIN: 7AT0DH12X17203968 Next Service: Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right hand taillight lens broken.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

RWD. Both rear tyres cord showing.

| Interior Comments | | |
|-------------------|---|--|
| Seats | Good n Drivers seat sign of wear. | |
| Carpets | Good | |
| Panels | Good n All doors arm rest sign of wear. | |
| Dashboard | Good | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

| | Pass | Fail | N/A | |
|--|------------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | <i>V V</i> | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | V | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | | | ~ | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 4 | .5 | mm | |
| Right front | 5.0 | | mm | |
| Left rear | ear 7 | | mm | |
| Right rear | 7 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | / | | | |
| Tail lights | ~ | | | |
| Indicators | \(\triangle \) | | | |
| Dashboard warning lights | | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | > > > > | | | |
| Window winder RL | ~ | | | |
| Window winder RR | | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | 1 | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ' | | | |
| Date: 16 Apr 2018 | | | | |

I have read and understood this condition guide.

Eddie Marsters

Name:

Signature: