

Report ID: 17,488,390 Version: 1 Created: 01 May 2018

Make: Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year: 2,008	Registration:	EQG948	Reg Expiry:	01 Jul 2018	Engine	I	1	I
WoF Expiry: 30 Apr 2019	Odometer:	197,165 Kms	Good No:	17488390	Oil level	~		
VIN: MMOUNYOE	40080650 Next Service:	207000	Service Histor	y: Yes	Smoke & fumes	~		
					Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System			
a full mechanical inspection	on prior to purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
					Performance	~		
Key: SC SC SC					Radiator / Hoses (visual)	~		
S = scratch					Transmission			
D = dent R = rust PT = paint defect					Operation	~		
					Noise	~		
C = crack					Clutch			~
P = pin dent	HA			74116	CV joints	~		
* = decals SC 919					Wheel bearings	~		
SC = stone chips					Brakes			
W = significant scuffs S SC					Performance	~		
Body Inspection Co	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Left side step plate bent					Tyres (lowest observed tread	d depth	of tyre	es)
					Left front	3.	.2	mm
					Right front	3.	.8	mm
					Left rear	2.		mm
Conditions During Body Inspection: Dry					Right rear	2.		mm
					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
					Suspension performance	~		
				Steering performance	~			
				Shock absorbers	~			
					Air Conditioning / Heater			
					Operation 🖌			
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
	Good				Tail lights	~		
Carpets					Indicators	~		
Panels	Good				Dashboard warning lights	~		
Dealth a suid	Good				Wipers (front & rear)	~		
Dashboard					Window winder FL	~		
					Window winder FR	~		
General Comments					Window winder RL	~		
					Window winder RR	<		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	2		
Road Conditions During Test Drive: Dry					Central locking	~		
	aniem. – · ·				Remote locking	~		
Engine Timing Mechanism: Cambelt					Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:					Reversing camera			~
Inspected by: Ian Dunn Date: 27 Apr 2018								

I have read and understood this condition guide.

Name:

Signature: