

Basic Vehicle Condition Guide

Report ID: 17,488,576

Version:


Created: 16 Apr 2018

Pass Fail N/A

Make: Model: Mazda 626 **Body Style:** Sedan Year: 1,998 Registration: Reg Expiry: ZY2250 26 Apr 2018 WoF Expiry: **Odometer:** 20 Jul 2018 **Good No:** 17488576 217,716 Kms VIN: JM0GF10S100102379 **Next Service: Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Wiper rusty

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

AC not working

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Xinghui Lin

Evidence of Cam Belt Replacement: γ_{es} Kr

Kms: 201,000

Engine			
Oil level	~		
Smoke & fumes	~		
Performance	V V		
Noise	~		
Cooling System		•	
Coolant condition	V V		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		5	mm
Right front		5	mm
Left rear	5 m		mm
Right rear		5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

I have read and understood this condition guide.

Name:			

Signature:	

16 Apr 2018

~

Reversing camera