

## Turners Certified Imports 50 Point Check

Report ID: 17,488,904

Version:

Created: 29 Mar 2019

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold

IMPORTED VEHICLES		rtest driver up to 30km/n nom cold.	
Make: Audi Body Style: Wagon Model: A6 Odometer: 80,825 Kms Year: 2009 VIN: WAUZZZ4F19N020836  Under Carriage & Under Bonnet Inspection Comments  General Comments		Panels: Good  Dashboard: Good  Engine Timing Mechanism:  Evidence of Cam Belt Replacemen	Timing Chain nt: Not Applicable
		Replaced At (odometer reading):  Road Conditions During Test Drive	<sub>e:</sub> Dry
Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5.0 mm
Head lights	Noise	Smoke & fumes	Right front 5.0 mm
Tail lights	Clutch	Performance	Left rear 4.0 mm
Indicators	CV joints	Noise	Right rear 5.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare N/A
Wipers (front & rear)	Wheel balance		Tools
Window winder FL	Brakes	Coolant condition	Interior
Window winder FR		Performance	-1
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RR	Hand Brake	Suspension	Heater fan
Poar view mirrors	Keys & Locking	Suspension performance	Seatbelts

**Central locking** 

Remote locking

Number of keys

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Reversing camera

1

Suspension performance

Steering performance

Inspected by: Jason Law

**Shock absorbers** 

Date: 05 Oct 2018

**X** = Fail = Not applicable for this vehicle

Horn

**Turners Certified Key** 

✓ = Pass