

Report ID: 17,489,636 Version: 2 Created: 01 May 2018

Make:	KIA	Model:	Sorento	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,015	Registration:	HZH519	Reg Expiry:	24 May 2018	Engine				
WoF Expiry:	08 Mar 2019	Odometer:	145,973 Kms	Good No:	17489636	Oil level	~			
VIN:	KNAKU814ME556450(Next Service:	152000	Service Histor	V: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:	S SC S	-0	s sc sc	-01-	S SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	s sc			ZIS	S SC	Operation	~			
PT = paint defe				$\left[\left(\right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HID				74 <u>11</u>	CV joints	~		-	
* = decals	ssc 91			-No-		Wheel bearings	~			
SC = stone chips						Brakes				
W = significan	scuffs SC		S SC		D SC	Performance	~			
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread	depth	of tyre	s)	
Crack in the windscreen ,									mm	
						Right front	4		mm	
						Left rear	4		mm	
						Right rear	6		mm	
Conditions During Body inspection. Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	Conditioning / Heater			
						Operation				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	Average					Tail lights	~			
Carpets	Avelage					Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
	1					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central lockin							~			
						Remote locking	~			
Engine Timing Mechanism: Unknown Sat. Nav. (basic test o									~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
·										
Inspected by: Donovan Matara Date: 01 May 2018										

I have read and understood this condition guide.

Name:

Signature: